

From: Whelan, Joseph <jwhelan1@usaw_net.com>
Sent: Friday, February 25, 2011 2:55 PM
To: 'Moxley.Bret@epamail.epa.gov'; 'Tyahla.Stephen@epamail.epa.gov';
'stuart.yamada@doh.hawaii.gov'; 'Steven.chang@doh.hawaii.gov';
'alec.wong@doh.hawaii.gov'
Subject: CQA Report for Liner Repairs to the Southwestern Section of Cell E6
Attach: Letter Report Cell E6 West Slope Repair_2-25-11.pdf; MSW Placement
Area_022111.pdf

Greetings all.

Please find attached the CQA report for the recently completed evaluation and repair to the liner located in the southwestern section of Cell E6. We would appreciate your timely review and approval of this report. Approval to place waste in this area is necessary in order for the landfill to reopen to the general public. Please contact me with any questions. Thank you.

Best regards,

<<...>> <<...>>

Joe Whelan

General Manager

Waste Management of Hawaii

808-668-2985, ext. 15 Office

808-668-1366 Fax

808-479-4610 Mobile

***Waste Management's landfills provide over 17,000 acres of
protected land for wildlife habitats and 15 landfills are certified
by the Wildlife Habitat Council.***